Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0106**

Resource Identification

Property Name(s): ..... House, Route 610 {Function/Location}
Property Date: 1870
Address(s): ..... Route 610 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Interior end	Brick	
Porch	Porch - 1-story, 3-bay	Wood	other
Roof	Roof - Gable	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Sash, double-hung	Wood	Windows - 2/2

WUZIT Count:

No.	Wuzit Types	Historic?
1	Barn	Undetermined
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Single Dwelling
Est. Date of Construction: .... 1870 ca {VDHR Survey File}
Accessed? .....
Primary Resource? ..... Yes
Number of Stories: 1.5
Architectural Style: ..... Other
Condition: .....
Interior Plan Type: ..... Central Passage, Single Pile
Threats to Resource: .....
Description: Architecture Summary: Half-story windows above porch. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Barn
Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: .....
Description: Architecture Summary: Log barn in rear End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Domestic

Significance Statement: Odd, late 19th century, true 1 1/2 story house.

Bibliographic Documentation

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Reconnaissance Survey
Date: ..... 1990/7 /4
Organization or Person: ..... Willie Graham
CRM Event Notes or Comments: ....

VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-106
Negative no(s).

City/Town/Village/Hamlet Windsor Vicinity
Street address or route number Rte. 610, .7 mi. north of Rte. 609
Historic name
County Isle of Wight
U.S.G.S. Quad Windsor
Common name

Present use Abandoned
Original use Dwelling
Building Style Vernacular
Building Date(s) late 19th century

1. Construction Materials

- ☒ wood frame
- ☐ brick
  - bond: ☐ English ☐ Flemish ☐ ____-course American ☐ stretcher ☐ other ____
- ☐ stone
  - ☐ random rubble
  - ☐ coursed rubble
  - ☐ ashlar ☐ dressed ☐ rock-faced
- ☐ log:
  - ☐ squared ☐ unsquared
  - notching:
  - ☐ V-notch ☐ half dovetail
  - ☐ saddle ☐ full dovetail
  - ☐ square ☐ diamond
- ☐ concrete block
- ☐ terra cotta
- ☐ steel frame
- ☐ other ____

2. Cladding Material

- ☒ weatherboard ☐ composition siding
- ☐ vertical siding ☐ stucco
- ☐ board & batten ☐ aluminum or vinyl siding
- ☐ shingle: ☐ cast iron
  - ☐ wood ☐ sheet metal
  - ☐ asbestos ☐ enameled metal
  - ☐ asphalt ☐ glass
- ☐ bricktex
- ☐ other ____



3. Stories (number) 1 1/2
- ☐ low basement ☐ raised basement

4. Bays (number): front 3 side (church) ____
- ☒ symmetrical ☐ asymmetrical

5. Roof Type
- ☐ shed
  - ☐ parapet?
- ☒ gable
  - ☐ pediment?
  - ☐ parapet?
  - ☐ clipped end?
  - ☐ cross gable?
  - ☐ central front gable?
- ☐ hipped
  - ☐ pyramidal?
- ☐ mansard
- ☐ false mansard
- ☐ gambrel
- ☐ flat
  - ☐ parapet?
- ☐ roof not visible
- ☐ other ____

6. Roofing Material
- ☐ shingle
  - ☐ composition (asphalt, asbestos, etc.)
  - ☐ wood
- ☒ metal
  - ☒ standing seam
  - ☐ corrugated
  - ☐ pressed tin (simulated shingles)
- ☐ tile
  - ☐ pantile ☐ flat ☐ glazed
- ☐ slate
- ☐ not visible

7. Dormers (number): front ____ side ____
- ☐ gable ☐ pediment?
- ☐ shed
- ☐ hipped

8. Primary Porch
style ____
stories 1
levels 1 bays 3
materials wood, standing seam tin
description and decorative details
Square, tapering wood columns, shed roof.

9. General supplementary description and decoration: Unbeaded weatherboards, interior brick stove chimneys, two-over-two sash. Half-story windows above porch.

10. Major additions and alterations: House replaced with mobile home.

11. Outbuildings: Log barn in rear.

12. Landscape Features:
Large sycamore & cedar trees in front yard.

13. Significance: Odd, late 19th-century, true 1 1/2-story house.

Surveyed by: Willie Graham Date: 7/4/90



FIGURE 9
Architectural Resources Identified During Survey